



QUESTIONS AND ANSWERS

BID No. 06/21

PHYSICAL ACCESS CONTROL UPGRADE OF THE GENERAL SERVICES BUILDING OF THE GENERAL SECRETARIAT OF THE ORGANIZATION OF AMERICAN STATES

Questions of interested companies.

Answers from the GS/OAS

1. Who is responsible for XRay of the slab and core drilling the holes?

Yes, the contractor will be responsible for providing the appropriate plans and details for core drilling and installation of turn style equipment on concrete flooring. The contractor will submit the names of any subcontractor that may be used for core drilling as part of the contract and the required and associated licensing.

2. Do we need to include badge IN & OUT Readers?

Yes, the contractor will be required to identify installation and cost estimates for turn style readers submitted for installation as part of this RFP.